



## Flat Washers - Pg Thread

Flat washer shields the surface by uniformly distributing load when tightening a bolt or screw and prevent corrosion. A washer is often placed under a machine screw to lessen noise and abrasion and offer electrical insulation. They are available in PG thread.

### Technical Data

|                   |                             |
|-------------------|-----------------------------|
| Material          | Nitrile, Black              |
| Temperature Range | -25° C to +100°C Continuous |
| Threads available | Pg Thread                   |

### Ordering Information

#### Pg Threads

| Cat. No.   | External Thread | Internal Thread | Size   | Thickness | Standard Pack (Pieces) |
|------------|-----------------|-----------------|--------|-----------|------------------------|
| WSH-Pg7    | 17              | 10.5            | Pg7    | 1.2       | 50                     |
| WSH-Pg9    | 20              | 14.5            | Pg9    | 1.2       | 50                     |
| WSH-Pg11   | 24.5            | 16.5            | Pg11   | 1.2       | 50                     |
| WSH-Pg13.5 | 25              | 18.5            | Pg13.5 | 1.5       | 50                     |
| WSH-Pg16   | 27              | 20.5            | Pg16   | 1.5       | 50                     |
| WSH-Pg21   | 34              | 26              | Pg21   | 1.5       | 50                     |
| WSH-Pg29   | 45              | 35              | Pg29   | 1.5       | 50                     |
| WSH-Pg36   | 56              | 45              | Pg36   | 1.5       | 50                     |
| WSH-Pg42   | 67              | 52.1            | Pg42   | 1.5       | 50                     |
| WSH-Pg48   | 69              | 57              | Pg48   | 1.5       | 25                     |