



Flat Washers - Pg Thread

Flat washer shields the surface by uniformly distributing load when tightening a bolt or screw and prevent corrosion. A washer is often placed under a machine screw to lessen noise and abrasion and offer electrical insulation. They are available in PG thread.

Technical Data

Material	Nitrile, Black
Temperature Range	-25° C to +100°C Continuous
Threads available	Pg Thread

Ordering Information

Pg Threads

Cat. No.	External Thread	Internal Thread	Size	Thickness	Standard Pack (Pieces)
WSH-Pg7	17	10.5	Pg7	1.2	50
WSH-Pg9	20	14.5	Pg9	1.2	50
WSH-Pg11	24.5	16.5	Pg11	1.2	50
WSH-Pg13.5	25	18.5	Pg13.5	1.5	50
WSH-Pg16	27	20.5	Pg16	1.5	50
WSH-Pg21	34	26	Pg21	1.5	50
WSH-Pg29	45	35	Pg29	1.5	50
WSH-Pg36	56	45	Pg36	1.5	50
WSH-Pg42	67	52.1	Pg42	1.5	50
WSH-Pg48	69	57	Pg48	1.5	25